Replies to Queries raised during Prebid Meeting on RM&U of Umiam - Umtru Stage — III Power Station (Tender for Package II - Rehabilitation of Hydromechanical and Civil Facilities) held on 24<sup>th</sup> June , 2024

Sl.	Queries raised by Bidder A	Replies by MePGCL
No. 1	Bill No.1/Item No. 111: The item mentions etc. but does not have any description, unit and quantity as provided	There are only ten items in Bill No. 1 (Item Nos. 101 to 110) which have to be quoted by the bidders.
2	for the preceding ten items.  Bill No. 14/Item No. 1407: Repair of roof of Power House does not specify the type of material/treatment to be used.	The materials and method of repair/treatment of the roof shall be as per Clause 6.2 (a) Normal Treatment provided in IS: 1346-1991 - Code of Practice for Waterproofing of Roofs with Bituminous Felts
3	Bill No. 20/item No.2005: The supply of 15 HP submersible pump does not mention the length of iron chain for the	The length of the iron chain shall be 25 (twenty five) metres.
4	pump.  Bill No. 22/Item No.2232: Capacity of water heater (geyser) for the Guest House is not mentioned.	The capacity of the water heater (geyser) shall be 15 (fifteen) litres.
5	Bill No. 28/Item No.2802: The item mentions drawing of 3-phase main line with wire length of 6 m for rewiring of extended security shed. The bidder wanted to know whether this includes supply/ provision of the wire.	Wherever the drawing of main/sub-main line is mentioned in any item, this includes supply of the materials by the contractor.

SI.	Queries raised by Bidder B	Replies by MePGCL
No. 1	The Performance Security Guarantee may be kept at 5% of the contract amount.	The Performance Security Guarantee is already kept at 5% of the contract amount in the Contract Data under the Particular Conditions of Contract.  The request is accepted. Addendum to the Bid Document to include radial gate will be issued in this regard as provided under ITB 8.
2	The qualification criterion under Clause 2.4 (b) (2) may be modified to include experience in installation/repair of radial gate /vertical lift gate and not vertical lift gate only, since radial gate is more complicated to instal / repair than vertical lift gate.	